


Android线屏镭射修复之思维导图

Android Lining Laser Repair Mind Map (COP)

故障原因：驱动IC的输出端，像素电路烧毁

Fault cause: The output of the driver IC, the pixel circuit burned



注意：

Attention:

- 1, 学习像素线测量系统的使用 ;
Learn the use of pixel line measurement system;
- 2, 学习像素线电路的短路规律 ;
Learn the short circuit law of pixel line circuit;
- 3, 使用导电性和稳定性更好的导电材料 ;
Use conductive materials with better conductivity and stability;