

IP线屏镭射修复之思维导图

IP Lining Laser Repair Mind Map (COP)

故障原因: 折弯位置裂痕

Fault cause: Crack in bending area



注意:

Attention:

- 1, 如果屏幕显示粗的白线, 维修成功率很低, 不建议维修;
If the screen shows a thick white line, the maintenance success rate is very low, not recommended maintenance;
- 2, 如果裂痕的宽度很大, 镭射将无法熔接电路, 屏幕的线无法修复;
If the width of the crack is large, the laser will not be able to weld the circuit, and the line of the screen cannot be repaired;
- 3, 屏幕出线的原因不只一种, 所以, 对折弯位置裂痕的判断很重要
There's more than one reason a screen lining. Therefore, the judgment of the bending area crack is very important;